

The Boeing Company  
P.O. Box 516  
St. Louis, MO 63166-0516  
(314) 232-0232 TELEX 44-857

REC'D  
APR 23 2002  
RCAP

464C-5271-JWH  
17 April 2002



Mr. Jerome Johnson  
U.S. Environmental Protection Agency Region VII  
901 North Fifth Street  
Kansas City, Kansas 66101

Enclosure: Corrective Action Quarterly Progress Report-First  
Quarter 2002

Dear Mr. Johnson:

The enclosed Quarterly Progress Report is submitted as required by Section XI. of the Corrective Action Conditions of the Hazardous Waste Management Facility Permit, Number MOD 000 818 963. Three copies of the report will also be submitted to the Missouri Department of Natural Resources as required under the terms of the permit.

Please contact me should you need additional information.

Sincerely,

A handwritten signature in black ink, appearing to read "Joe Haake", written in a cursive style.

Joseph W. Haake, Group Manager  
Environmental and Hazardous Materials Services  
Dept. 464C, Bldg. 220, Mailcode S221-1400  
(314) 232-6941



R00410116  
RCRA RECORDS CENTER

## **Quarterly Progress Report for First Quarter 2002**

### **Description of the work completed**

An Annual Monitoring Report for SWMU 17 was submitted to MDNR on January 25, 2002. The report documents the investigation activities conducted to characterize the nature of any hazardous waste/constituent released to soil or groundwater from the unit. The report provides an evaluation and conclusions regarding the RFI investigation data and includes plans for additional investigation.

### **Summary of all findings**

Laboratory analysis of samples collected from SWMU #17 are presented in the Annual Monitoring Report.

### **Summary of all problems or potential problems and actions taken to rectify problems**

Monitoring wells MW25-1 and MW25-5A at the Former Fabrication Operations Facility were damaged during snow removal. The wells were repaired during the first quarter. Monitoring well MW25-5C was covered over with concrete during construction activities at the site. The concrete will be removed and any damage to the well will be repaired during second quarter.

### **Projected work for the next reporting period**

Upon MDNR approval, install additional borings at SWMU #17 as, described in the Annual Monitoring Report, to determine the extent of contamination to the south.

Begin the pilot study at the Former Fabrication Operations Facility upon receipt of an injection permit from MDNR.

### **Instances of noncompliance with the corrective actions of the permit**

None

## **Quarterly Progress Report for First Quarter 2002**

### **Description of the work completed**

An Annual Monitoring Report for SWMU 17 was submitted to MDNR on January 25, 2002. The report documents the investigation activities conducted to characterize the nature of any hazardous waste/constituent released to soil or groundwater from the unit. The report provides an evaluation and conclusions regarding the RFI investigation data and includes plans for additional investigation.

### **Summary of all findings**

Laboratory analysis of samples collected from SWMU #17 are presented in the Annual Monitoring Report.

### **Summary of all problems or potential problems and actions taken to rectify problems**

Monitoring wells MW25-1 and MW25-5A at the Former Fabrication Operations Facility were damaged during snow removal. The wells were repaired during the first quarter. Monitoring well MW25-5C was covered over with concrete during construction activities at the site. The concrete will be removed and any damage to the well will be repaired during second quarter.

### **Projected work for the next reporting period**

Upon MDNR approval, install additional borings at SWMU #17 as, described in the Annual Monitoring Report, to determine the extent of contamination to the south.

Begin the pilot study at the Former Fabrication Operations Facility upon receipt of an injection permit from MDNR.

### **Instances of noncompliance with the corrective actions of the permit**

None